

CONSTRUCTION EQUIPMENT VOLVO L70H 624368 - HYDRAULIC POWER PACK



Sample No: VCP0008730
Oil Type: {unknown}

Job No:

102 1101				
VOLVO				
SAMPLE	INFORMATION			
Sample Number	-	VCP0008730	 	
Sample Date		21 Jun 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
	_			
Visc @ 40°C	cSt	43.2	 	
Acid Number (AN	N) mg KOH/g	■ 0.36	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Particles >4µm		14168	 	
Particles >6µm		2045	 	
Particles > 14µm		104	 	
ISO 4406:1999 (c))	21/18/14	 	
Silicon	ppm	2	 	
Sodium	ppm	2	 	
Potassium	ppm	■0	 	
WEAR M	AFTAI S			
_				
Iron	ppm	6	 	
Copper	ppm	1	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum Chromium	ppm	= <1	 	
Molybdenum	ppm	■<1		
Nickel	ppm	< 1 1 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
Variadiditi	PPIII			
VOLVO				
ADDITIV	/ES			
Calcium	ppm	64	 	
Magnesium	ppm	3	 	
Zinc	ppm	405	 	
Phosphorus	ppm	351	 	
Barium	ppm	0	 	
Boron	ppm	0	 	



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0092Unique No:11110848Signed:Don BaldridgeReport Date:06 Jul 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

