



CONSTRUCTION EQUIPMENT

PETERBILT 337 FM307819 - REAR AXLE



Sample No: VCP446686
Oil Type: MOBIL 75W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP446686	---	---	---
Sample Date	01 Jul 2024	---	---	---
Machine Hours	8800	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

SILVERPOINT ENTERPRISES
 637N 2743E
 ROBERTS, ID
 US 83444
 Contact: BRADLEY HAHN
 silverpointenterprises20@gmail.com
 T: (208)270-1141
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 96.6	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 60	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 163	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 11	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 21	---	---	---
Magnesium	ppm	3	---	---	---
Zinc	ppm	█ 13	---	---	---
Phosphorus	ppm	1483	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 225	---	---	---

Depot: SILROBID
Unique No: 11111381
Signed: Don Baldrige
Report Date: 07 Jul 2024



CONSTRUCTION EQUIPMENT



GRAPHS

