



CONSTRUCTION EQUIPMENT

VOLVO A45G 352205 - COOLANT



Sample No: VCP0008490

Oil Type: {unknown}

Job No:



SAMPLE INFORMATION

Sample Number	VCP0008490	---	---	---
Sample Date	27 Jun 2024	---	---	---
Machine Hours	8083	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: SHAWN NORTHCRAFT
shawn.northcraft@altg.com

T: (904)737-6000

F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	■ 8.41	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 48.5	---	---	---
Freezing Point	°C	■ -31	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO0092

Unique No: 11111535

Signed: Jonathan Hester

Report Date: 08 Jul 2024

Submitted By: TECHNICIAN ACCOUNT




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

