

## **CONSTRUCTION EQUIPMENT** VOLVO A40G 752239 - DIESEL ENGINE



Sample No: VCP450516

VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

**Oil Type:** Job No:

				E
	IFORMATION		 	
Sample Number		VCP450516	 	
Sample Date		05 Jul 2024		 ALTA EC
Machine Hours		711	 	 5151 DR
Oil Hours		0		FORT M
		Changed	 	 US 3390
Oil Changed		_		Contact:
Sample Status		ABNORMAL	 	
VOLVO				tlark@al T:
VIL CONDI	TION			
Visc @ 100°C	cSt	<b>10.7</b>	 	 F: (239)4
Base Number (BN)		4.5	 	
Oxidation (PA)	%	59	 	 Diagn
	70	55		Oil and
VOLVO				 samplir
V CONTAMIN	IATION			correcti
Water	%	NEG	 	 this tim
Soot %	%	0.2	 	 service
Nitration (PA)	%	82	 	 is indic
Sulfation (PA)	%	61	 	 There is
Glycol	%	NEG	 	 contam
Fuel	%	0.4	 	 viscosit
Silicon		29	 	 BN resu
Sodium	ppm	<b>4</b>	 	 suitable Confirm
	ppm			 Comm
Potassium	ppm	<b>■</b> 4	 	
VOLVO				
WEAR MET	TALS			
Iron	ppm	21	 	
Copper	ppm	<b>162</b>	 	
Lead	ppm	□ <1	 	
Tin	ppm	<b>4</b>	 	
Aluminum	ppm	3	 	
Chromium		0	 	
	ppm	82	 	
Molybdenum Nickel	ppm	▲ 8	 	
Titanium	ppm	8		
	ppm		 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
VOLVO			 	
Calcium	ppm	2169	 	
Magnesium	ppm	75	 	
Zinc		1158	 	
	ppm			
Phosphorus Barium	ppm	987	 	
Barium	ppm	0	 	 Depot:
Boron	ppm	<b>16</b>	 	 Unique N

## MENT COMPANY

RTIN LUTHER KING BLVD S, FL DD LARK uipfl.com 3302

change at the time of as been noted. No ction is recommended at esample at the next val to monitor.Valve wear Fuel content negligible. indication of any ion in the oil. The oil ower than normal. The dicates that there is alinity remaining in the oil. type.

VOLVO0090 11115403 Sean Felton Signed: Report Date: 12 Jul 2024


Contact/Location: TODD LARK - VOLVO0090

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Contact/Location: TODD LARK - VOLVO0090