



# CONSTRUCTION EQUIPMENT

HERC RENTALS VOLVO L70H 623495 - FRONT AXLE



**Sample No:** VCP453863  
**Oil Type:** TDH FLUID SAE 75W80  
**Job No:** HERC RENTALS



## SAMPLE INFORMATION

Sample Number	VCP453863	---	---	---
Sample Date	09 Jul 2024	---	---	---
Machine Hours	2267	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**VCES- VOLVO CONSTRUCTION EQUIPMENT**  
 22099 KNABE ROAD  
 CORONA, CA  
 US 92883  
 Contact: OSCAR DEL CAMPO  
 oscar.delcampo@vcesvolvo.com  
 T: (951)277-7620  
 F: (951)277-4550



## OIL CONDITION

Visc @ 40°C	cSt	█ 40.5	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 18	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ <1	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 95	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ 11	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 9	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 3726	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1475	---	---	---
Phosphorus	ppm	█ 1297	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 110	---	---	---

**Depot:** VOLVO4486  
**Unique No:** 11116075  
**Signed:** Don Baldrige  
**Report Date:** 12 Jul 2024




# CONSTRUCTION EQUIPMENT



## GRAPHS


### Iron (ppm)




### Lead (ppm)



### Aluminum (ppm)




### Chromium (ppm)



### Copper (ppm)



### Silicon (ppm)



### Viscosity @ 40°C



### Additives

