



CONSTRUCTION EQUIPMENT

VOLVO A40G 752239 - TRANSMISSION (AUTO)



Sample No: VCP450524
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



SAMPLE INFORMATION

Sample Number	VCP450524	---	---	---
Sample Date	05 Jul 2024	---	---	---
Machine Hours	711	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ABNORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 29.0	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 1	---	---	---



WEAR METALS

Iron	ppm	█ 16	---	---	---
Copper	ppm	█ 8	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 6	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 81	---	---	---
Magnesium	ppm	█ 3	---	---	---
Zinc	ppm	█ 9	---	---	---
Phosphorus	ppm	█ 195	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 78	---	---	---

Diagnosis

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0090
Unique No: 11116145
Signed: Don Baldrige
Report Date: 12 Jul 2024



CONSTRUCTION EQUIPMENT



GRAPHS


Iron (ppm)




Lead (ppm)



Aluminum (ppm)




Chromium (ppm)




Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Additives

