
CONSTRUCTION EQUIPMENT X39607 3148 - REAR AXLE



VOLVO

	VCP429791			
	03 Jul 2024			
	7028			
	0			
	N/A			
	NORMAL			
FION				
cSt	50.5			
IATION				
%	NEG			
ppm	15			
ppm	4			
ppm	0			
TALS				
ppm	20			
	4			
	0			
	0			
	∎1			
ppm	<1			
ppm	8			
ppm	0			
ppm	0			
ppm	0			
ppm	∎1			
ppm	0			
	cSt ATION % ppm ppm ppm ppm ppm ppm ppm ppm ppm p	03 Jul 2024 7028 0 N/A NORMAL ION cSt 50.5 ATION % NEG ppm 15 ppm 4 ppm 0 FALS ppm 20 ppm 0 ppm 0	03 Jul 2024 7028 0 N/A NORMAL ION cSt 50.5 ATION % NEG ppm 15 ppm 4 ppm 0 ppm 0 ppm 15 ppm 0 ppm 0 ppm 20 ppm 0 ppm 0	03 Jul 2024 7028 0 N/A NORMAL rcN rppm 15 ppm 0 rppm 14 ppm 0 ppm 0 ppm 1 ppm 0

SCOTT EQUIPMENT COMPANY LLC - Baton Rouge 10160 AIRLINE HWY BATON ROUGE, LA US 70816 Contact: BRENT CALDWELL bcaldwell@scottcompanies.com T: (225)293-3683 F: (225)292-9658

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

vun	uui	un	
		н.	
1	1	<u>.</u>	
VO	13/76		

Calcium	ppm	3385						
Magnesium	ppm	57						
Zinc	ppm	1303						
Phosphorus	ppm	1107						
Barium	ppm	0						
Boron	ppm	105						

Depot: VOLVO6242 Unique No: 11117048 Signed: Don Baldridge Report Date: 13 Jul 2024




CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Contact/Location: BRENT CALDWELL - VOLVO6242