## **CONSTRUCTION EQUIPMENT** HER RENTALS VOLVO L110H 632557 - TRANSMISSION (AUTO)



Sample No: VCP444379 **Oil Type:** 

VOLVO

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No:

HFR RENTALS

## SAMPLE INFORMATION VCP444379 Sample Number VCP432218 Sample Date 09 Jul 2024 28 Dec 2023 Machine Hours 2420 1206 Oil Hours 0 0 Not Changd Oil Changed N/A NORMAL Sample Status ATTENTION **OIL CONDITION** Visc @ 40°C cSt 29.4 29.0 CONTAMINATION Water % NEG NEG Silicon 6 ppm 7 Sodium 0 🔲 3 ppm Potassium ppm 2 < 1</p> WEAR METALS Iron ppm 92 37 Copper ppm 10 5 Lead ppm 0 🔲 0 Tin ppm <1 0 Aluminum 4 2 ppm Chromium □ <1 0 ppm Molybdenum ppm 4 1 Nickel ■ <1 0 ppm Titanium ppm <1 0 Silver **||** <1 0 ppm Manganese ppm 3 3 ppm <1 0



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Vanadium

01 **ADDITIVES** Calcium ppm 178 104 Magnesium 37 14 ppm 33 Zinc ppm 95 Phosphorus 279 213 ppm Barium 2 0 ppm 84 85 Boron ppm

> Depot: **VOLVO0093** Unique No: 11124130 Signed: Wes Davis **Report Date:** 15 Jul 2024 Contact/Location: KENNY HANEY - VOLVO0093

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

