

CONSTRUCTION EQUIPMENTVOLVO A40G 352700 - TRANSMISSION (AUTO)



Sample No: VCP449686

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No:

SAMPLE	INFORMATIO	N		
Sample Number		VCP449686	 	
Sample Date		11 Jul 2024	 	
Machine Hours		4716	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
VOLVO	DITION			
OIL CON				
Visc @ 40°C	cSt	21.8	 	
VOLVO				
CONTAM	IINATION			
Water	%	NEG	 	
Silicon	ppm	8	 	
Sodium	ppm	4	 	
Potassium	ppm	2	 	
Otassiani	PPIII			
VOLVO				
WEAR M	IF I ALS			
Iron	ppm	1 3	 	
Copper	ppm	■ 7	 	
Lead	ppm	■0	 	
Tin	ppm	■<1	 	
Aluminum	ppm	6	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	■ 0	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	0	 	
Silver	ppm	■0	 	
Manganese	ppm	■ <1	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	5 1	 	
Magnesium	ppm	0	 	
Zinc	ppm	■0	 	
Phosphorus	ppm	181	 	
Barium	ppm	0	 	
Boron	ppm	■86	 	
	Phili			



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

1:

F: (239)481-3302

Diagnosis

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0090Unique No:11125501Signed:Don BaldridgeReport Date:17 Jul 2024



CONSTRUCTION EQUIPMENT





