

## CONSTRUCTION EQUIPMENT 38526 TAKEUCHI TL 10V2 412004687 - DIESEL FUEL



Sample No: VCP438638

Oil Type: No.2 DIESEL FUEL (ULTRALOW SULPHUR)

Report Id: COWMAB [WUSCAR] 06236690 (Generated: 07/18/2024 06:57:35) Rev: 1

**Job No:** 38526

| -<br>-<br>- |
|-------------|
| -           |
| -           |
|             |
| -           |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |
|             |



## COWIN EQUIPMENT - ATLANTA 5710 RIVERVIEW RD MABLETON, GA US 30126 Contact: MIKE ANDREWS mandrews@cowin.com

T: (404)690-7210

F:

## Diagnosis

We recommend you service the filters on this component. All metal levels are normal indicating no corrosion in the system. Moderate concentration of visible dirt/debris present in the fuel. The water content is negligible. The condition of the fuel is acceptable for the time in service.

Depot:COWMABUnique No:11125524Signed:Jonathan HesterReport Date:17 Jul 2024



## **CONSTRUCTION EQUIPMENT**





