CONSTRUCTION EQUIPMENT 729177 MOSAIC VOLVO EC380 315267 - HYDRAULIC SYSTEM

Sample No:VCP445598Oil Type:VOLVO SUPER HYDRAULIC OIL 46Job No:729177 MOSAIC

### SAMPLE INFORMATION

ZOTAZ

Sample Number		VCP445598	VCP408654	 
Sample Date		13 Jun 2024	10 May 2023	 
Machine Hours		1033	496	 
Oil Hours		1033	0	 
Oil Changed		Not Changd	Not Changd	 
Sample Status		ABNORMAL	NORMAL	 
OIL CONDI	IUN			
Visc @ 40°C	cSt	42.3	43.0	 
Acid Number (AN)	mg KOH/g	0.46	0.53	 
	ATION			

Water	%	NEG	NEG	 
Particles >4µm		🔺 126853	5437	 
Particles >6µm		<b>6</b> 52782	1216	 
Particles >14µm		<b>1649</b>	60	 
ISO 4406:1999 (c)	)	24/23/18	20/17/13	 
Silicon	ppm	3	□ <1	 
Sodium	ppm	□ <1	0	 
Potassium	ppm	0	0	 

#### WEAR METAL

WCAR I				
Iron	ppm	2	1	 
Copper	ppm	24	15	 
Lead	ppm	0	0	 
Tin	ppm	0	0	 
Aluminum	ppm	□<1	0	 
Chromium	ppm	0	0	 
Molybdenum	ppm	0	0	 
Nickel	ppm	0	0	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	0	0	 
Vanadium	ppm	0	0	 

VOLVO

Calcium	ppm	91	97		
Magnesium	ppm	<b>1</b>	0		
Zinc	ppm	545	547		
Phosphorus	ppm	<b>434</b>	413		
Barium	ppm	0	0		
Boron	ppm	0	0		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

#### Diagnosis

The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

 Depot:
 VOLVO0093

 Unique No:
 11126527

 Signed:
 Wes Davis

 Report Date:
 17 Jul 2024

Report Id: VOLVO0093 [WUSCAR] 06237693 (Generated: 07/17/2024 09:35:23) Rev: 1


Contact/Location: JOHN FARDELLA - VOLVO0093

## **CONSTRUCTION EQUIPMENT**



# GRAPHS

VOLVO



Contact/Location: JOHN FARDELLA - VOLVO0093