



CONSTRUCTION EQUIPMENT

729177 MOSAIC VOLVO EC380 315267 - REAR RIGHT FINAL DRIVE



Sample No: VCP445602
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: 729177 MOSAIC



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP445602	VCP408641	---	---
Sample Date	13 Jun 2024	10 May 2023	---	---
Machine Hours	1033	496	---	---
Oil Hours	500	0	---	---
Oil Changed	Changed	Not Chngd	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 145	█ 151	---	---
-------------	-----	-------	-------	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	█ 26	█ 10	---	---
Sodium	ppm	█ 1	█ 2	---	---
Potassium	ppm	█ 3	█ 2	---	---



WEAR METALS

Iron	ppm	█ 310	█ 156	---	---
Copper	ppm	█ <1	█ <1	---	---
Lead	ppm	█ 0	█ 0	---	---
Tin	ppm	█ 0	█ 0	---	---
Aluminum	ppm	█ 2	█ <1	---	---
Chromium	ppm	█ 9	█ 4	---	---
Molybdenum	ppm	█ <1	█ <1	---	---
Nickel	ppm	█ <1	█ <1	---	---
Titanium	ppm	<1	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	█ 5	█ 4	---	---
Vanadium	ppm	<1	0	---	---



ADDITIVES

Calcium	ppm	█ 0	█ 23	---	---
Magnesium	ppm	█ 2	█ <1	---	---
Zinc	ppm	█ 12	█ 13	---	---
Phosphorus	ppm	█ 284	█ 289	---	---
Barium	ppm	█ 0	█ 0	---	---
Boron	ppm	█ <1	█ 0	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 11127019
Signed: Sean Felton
Report Date: 18 Jul 2024



CONSTRUCTION EQUIPMENT



GRAPHS

