



# CONSTRUCTION EQUIPMENT

578360 T AND K VOLVO A45G 352823 - REAR AXLE



**Sample No:** VCP442130  
**Oil Type:** VOLVO PREMIUM GEAR OIL 80W-90 GL-5  
**Job No:** 578360 T AND K



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: KENNY HANEY  
 khaney@flaglerce.com  
 T: (813)630-0077  
 F: (813)630-2233



## SAMPLE INFORMATION

Sample Number	VCP442130	---	---	---
Sample Date	10 Jun 2024	---	---	---
Machine Hours	4183	---	---	---
Oil Hours	3000	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 47.8	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 3	---	---	---



## WEAR METALS

Iron	ppm	█ 274	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ 4	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 7	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 74	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 44	---	---	---
Phosphorus	ppm	2227	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 207	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0093  
**Unique No:** 11127037  
**Signed:** Sean Felton  
**Report Date:** 18 Jul 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

