



CONSTRUCTION EQUIPMENT

717710 MOSAIC VOLVO A45G 752275 - TRANSMISSION (AUTO)



Sample No: VCP439769
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 717710 MOSAIC



SAMPLE INFORMATION

Sample Number	VCP439769	---	---	---
Sample Date	04 Jun 2024	---	---	---
Machine Hours	584	---	---	---
Oil Hours	584	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: JOHN FARDELLA
 john.fardella@altg.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█ 29.5	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 11	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 28	---	---	---
Copper	ppm	█ 38	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 16	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 71	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 2	---	---	---
Phosphorus	ppm	█ 183	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 76	---	---	---

Depot: VOLVO0093
Unique No: 11127111
Signed: Sean Felton
Report Date: 18 Jul 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

