



CONSTRUCTION EQUIPMENT

SPM715231 SENNEBOGEN 835ME 835.0.3282 - REAR AXLE



Sample No: VCP446413
Oil Type: GEAR OIL SAE 80W90
Job No: SPM715231



SAMPLE INFORMATION

Sample Number	VCP446413	VCP424692	---	---
Sample Date	25 Jun 2024	08 Dec 2023	---	---
Machine Hours	1200	223	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

BELSON STEEL

1685 N STATE RTE 50
BOURBONNAIS, IL
US 60914
Contact: M. POZAN
mpozan@belsonsteel.com
T: (815)932-7416
F:



OIL CONDITION

Visc @ 40°C	cSt	█ 149	█ 180	---	---
-------------	-----	-------	-------	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	█ 6	█ 2	---	---
Sodium	ppm	█ 3	█ 2	---	---
Potassium	ppm	█ 2	█ 0	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 157	█ 50	---	---
Copper	ppm	█ 7	█ 18	---	---
Lead	ppm	█ <1	█ 0	---	---
Tin	ppm	█ 0	█ 0	---	---
Aluminum	ppm	█ 2	█ 0	---	---
Chromium	ppm	█ 2	█ 0	---	---
Molybdenum	ppm	█ <1	█ 0	---	---
Nickel	ppm	█ <1	█ 0	---	---
Titanium	ppm	1	0	---	---
Silver	ppm	1	0	---	---
Manganese	ppm	█ 2	█ <1	---	---
Vanadium	ppm	<1	0	---	---



ADDITIVES

Calcium	ppm	█ 52	█ 7	---	---
Magnesium	ppm	█ 7	█ 0	---	---
Zinc	ppm	█ 28	█ 13	---	---
Phosphorus	ppm	█ 593	█ 1140	---	---
Barium	ppm	█ 1	█ 356	---	---
Boron	ppm	█ 9	█ 12	---	---

Depot: BELBOU
Unique No: 11129501
Signed: Wes Davis
Report Date: 19 Jul 2024



CONSTRUCTION EQUIPMENT



GRAPHS

