### **OIL ANALYSIS REPORT**

# VOLVO PENTA

#### SGM325BH7 - DIESEL FUEL R1-22284

Sample No: VPA055956

**Oil Type:** No.2 DIESEL FUEL (LOW-SULPHUR)

| Sample Number  | r   | VPA055956   | <br> |  |   |
|----------------|-----|-------------|------|--|---|
| Sample Date    |     | 25 Oct 2023 | <br> |  | CULLEN  |
| Machine Hours  |     | 0           | <br> |  | 9300 19   |
| Sample Status  |     | NORMAL      | <br> |  | SURREY<br>CA V41  |
| FUEL CONDITION | N   |             |      |  | Contact<br>mns@ci   |
| Sulfur         | ppm | 22          | <br> |  | T: (604)8   |
| Visc @ 40°C    | cSt | 3.3         | <br> |  | F:  |
| CONTAMINATIO   | N   |             |      |  |   |
| _ead           | ppm | 0           | <br> |  | Diagno<br>Please co<br>informat<br>sampling<br>applicab<br>any cont |
| Vickel         | ppm | 0           | <br> |  |   |
| Aluminum       | ppm | 0           | <br> |  |   |
| Vanadium       | ppm | 0           | <br> |  |   |
| Silicon        | ppm | 0           | <br> |  |   |

#### L POWER - 695335

elle Sayers esel.com 11

your representative for garding the proper for your service.{not ere is no indication of ation in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

Depot: CULSUR Unique No: 5682045 Signed: Kevin Marson Report Date: 20 Nov 2023

Contact/Location: Michelle Sayers - CULSUR

## **OIL ANALYSIS REPORT**



### GRAPHS

