

OIL ANALYSIS REPORT



R1-23836 27B03788 - DIESEL FUEL

Sample No: VPA057093

Oil Type: No.2 DIESEL FUEL (ULTRALOW SULPHUR)

SAMPLE INFORMATION

| | | | | |
|---------------|-------------|-----|-----|-----|
| Sample Number | VPA057093 | --- | --- | --- |
| Sample Date | 08 Feb 2024 | --- | --- | --- |
| Machine Hours | 548 | --- | --- | --- |
| Sample Status | NORMAL | --- | --- | --- |

FUEL CONDITION

| | | | | | |
|-------------|-----|-------|-----|-----|-----|
| Sulfur | ppm | ■ 6 | --- | --- | --- |
| Visc @ 40°C | cSt | ■ 2.7 | --- | --- | --- |

CONTAMINATION

| | | | | | |
|----------|-----|-----|-----|-----|-----|
| Lead | ppm | ■ 0 | --- | --- | --- |
| Nickel | ppm | ■ 0 | --- | --- | --- |
| Aluminum | ppm | ■ 0 | --- | --- | --- |
| Vanadium | ppm | 0 | --- | --- | --- |
| Silicon | ppm | ■ 0 | --- | --- | --- |

CULLEN DIESEL POWER - 695335

9300 192 ST

SURREY, BC

CA V4N 3R8

Contact: Michelle Sayers

mns@cullendiesel.com

T: (604)888-1211

F:

Diagnosis

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

Depot: CULSUR

Unique No: 5746086

Signed: Kevin Marson

Report Date: 11 Mar 2024

OIL ANALYSIS REPORT

**VOLVO
PENTA**

GRAPHS

