# VOLVO PENTA

### **OIL ANALYSIS REPORT**

#### PE4045N034686 - DIESEL FUEL R1-23893

Sample No: VPA054395

**Oil Type:** No.2 DIESEL FUEL (ULTRALOW SULPHUR)

Sample Numbe	r	VPA054395	 	
Sample Date		07 Feb 2024	 	 CULLEN DIESEL
Machine Hours		44	 	 9300 192 ST
Sample Status		NORMAL	 	 SURREY, BC CA V4N 3R8
FUEL CONDITIO		<b>— E</b>		mns@cullendiese
Sulfur Visc @ 40°C	ppm cSt	<b>5 2.2</b>	 	 T: (604)888-1211 F:
CONTAMINATIO	DN			
Lead	ppm	0	 	 Diagnosis
Nickel	ppm	0	 	 Please contact y
Aluminum	ppm	0	 	 information rega sampling kits for
Vanadium	ppm	0	 	 applicable} There
Silicon	ppm	0	 	 any contaminatio

#### POWER - 695335

Sayers l.com

our representative for arding the proper your service.{not is no indication of on in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

Depot: CULSUR Unique No: 5746095 Signed: Kevin Marson Report Date: 11 Mar 2024

Contact/Location: Michelle Sayers - CULSUR

## **OIL ANALYSIS REPORT**



### GRAPHS

### Pensky-Martens Flash Point (°C)

	-1			5	emperatur	ature	د				
	0.	-8 -	-6 -	-4.	.2.	0.	2.	4.	6.	8.	
L-4.7 /0 /										I	
Leo //Z4											
Feb7/24.			Ì	1	1		T T				