

OIL ANALYSIS REPORT



R1-24130 PE4045D977355 - DIESEL FUEL

Sample No: VPA052197

Oil Type: No.2 DIESEL FUEL (ULTRALOW SULPHUR)

SAMPLE INFORMATION

| | | | | |
|---------------|-------------|-----|-----|-----|
| Sample Number | VPA052197 | --- | --- | --- |
| Sample Date | 14 Mar 2024 | --- | --- | --- |
| Machine Hours | 220 | --- | --- | --- |
| Sample Status | NORMAL | --- | --- | --- |

FUEL CONDITION

| | | | | | |
|-------------|-----|-------|-----|-----|-----|
| Sulfur | ppm | ■ 4 | --- | --- | --- |
| Visc @ 40°C | cSt | ■ 2.4 | --- | --- | --- |

CONTAMINATION

| | | | | | |
|----------|-----|-----|-----|-----|-----|
| Lead | ppm | ■ 0 | --- | --- | --- |
| Nickel | ppm | ■ 0 | --- | --- | --- |
| Aluminum | ppm | ■ 0 | --- | --- | --- |
| Vanadium | ppm | 0 | --- | --- | --- |
| Silicon | ppm | ■ 0 | --- | --- | --- |

CULLEN DIESEL POWER - 695335

9300 192 ST

SURREY, BC

CA V4N 3R8

Contact: Michelle Sayers

mns@cullendiesel.com

T: (604)888-1211

F:

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

Diagnosis

Depot: CULSUR

Unique No: 5759380

Signed: Kevin Marson

Report Date: 03 Apr 2024

OIL ANALYSIS REPORT

**VOLVO
PENTA**

GRAPHS

