### **OIL ANALYSIS REPORT**

# OLVO ENTA

### NO UNIT VPA052250 - DIESEL FUEL

Sample No: VPA052250

Oil Type: No.2 DIESEL FUEL (ULTRALOW SULPHUR)

SAMPLE INFOR Sample Numbe		VPA052250	 	
Sample Date		25 Mar 2024	 	 CULLEN DIESEL POWER - 69
Machine Hours	;	1033	 	 9300 192 ST
Sample Status		NORMAL	 	 SURREY, BC CA V4N 3R8
FUEL CONDITIO	N			Contact: Michelle Sayers mns@cullendiesel.com
Sulfur	ppm	7	 	 T: (604)888-1211
Visc @ 40°C	cSt	3.6	 	 F:
CONTAMINATIO	ON			Diagnosis
Lead	ppm	0	 	 Diagnosis
Nickel	ppm	0	 	 Please contact your represent information regarding the pro-
Aluminum	ppm	0	 	 sampling kits for your service
Vanadium	ppm	0	 	 applicable} There is no indica
Silicon	ppm	<b>■</b> <1	 	 any contamination in the

95335

ntative for roper . e.{not ation of component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

Depot: CULSUR 5760672 Unique No: Signed: Kevin Marson Report Date: 09 Apr 2024 Contact/Location: Michelle Sayers - CULSUR

## **OIL ANALYSIS REPORT**



#### GRAPHS

#### Pensky-Martens Flash Point (°C)

	10.	Т		 			 	 							 					 						-				
	8																													I I I I
	6																													
	4	+ -																												1 T - T
°C	2	+ 1	1																											1
temperature °C	0	ł																												
tem	-2	+ 1																												
	-4	+ -																												
	-6	t																												
	-8 -	t																												
	-10-	L	-	 	 	 _	 	 	 _	_	 _	 	 	 _	 _	 	_	 	 	 	 	_	 _	 	 		_	_	_	-
		NU-SEVA	47/07101/1																										A CLOCK	L7/C7IPINI