

# OIL ANALYSIS REPORT



## R1-23554 KOHLER 362325 - DIESEL FUEL

**Sample No:** VPA052241  
**Oil Type:** No.2 DIESEL FUEL (ULTRALOW SULPHUR)

### SAMPLE INFORMATION

|               |             |     |     |     |
|---------------|-------------|-----|-----|-----|
| Sample Number | VPA052241   | --- | --- | --- |
| Sample Date   | 03 Apr 2024 | --- | --- | --- |
| Machine Hours | 5898        | --- | --- | --- |
| Sample Status | NORMAL      | --- | --- | --- |

### FUEL CONDITION

|             |     |       |     |     |     |
|-------------|-----|-------|-----|-----|-----|
| Sulfur      | ppm | ■ 9   | --- | --- | --- |
| Visc @ 40°C | cSt | ■ 2.3 | --- | --- | --- |

### CONTAMINATION

|          |     |     |     |     |     |
|----------|-----|-----|-----|-----|-----|
| Lead     | ppm | ■ 0 | --- | --- | --- |
| Nickel   | ppm | ■ 0 | --- | --- | --- |
| Aluminum | ppm | ■ 0 | --- | --- | --- |
| Vanadium | ppm | 0   | --- | --- | --- |
| Silicon  | ppm | ■ 0 | --- | --- | --- |

### CULLEN DIESEL POWER - 695335

9300 192 ST  
SURREY, BC  
CA V4N 3R8  
Contact: Michelle Sayers  
mns@cullendiesel.com  
T: (604)888-1211  
F:

### Diagnosis

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

**Depot:** CULSUR  
**Unique No:** 5761735  
**Signed:** Kevin Marson  
**Report Date:** 12 Apr 2024

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## GRAPHS

