

# OIL ANALYSIS REPORT



**R1-23969 RG6090L115969 - DIESEL FUEL**

**Sample No:** VPA052211

**Oil Type:** No.2 DIESEL FUEL (ULTRALOW SULPHUR)

## SAMPLE INFORMATION

Sample Number	VPA052211	---	---	---
Sample Date	10 Apr 2024	---	---	---
Machine Hours	300	---	---	---
Sample Status	NORMAL	---	---	---

## FUEL CONDITION

Sulfur	ppm	■ 4	---	---	---
Visc @ 40°C	cSt	■ 2.8	---	---	---

## CONTAMINATION

Lead	ppm	■ 0	---	---	---
Nickel	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	■ 0	---	---	---

**CULLEN DIESEL POWER - 695335**

9300 192 ST

SURREY, BC

CA V4N 3R8

Contact: Michelle Sayers

mns@cullendiesel.com

T: (604)888-1211

F:

## Diagnosis

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

**Depot:** CULSUR

**Unique No:** 5772572

**Signed:** Kevin Marson

**Report Date:** 25 Apr 2024

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## GRAPHS

