

OIL ANALYSIS REPORT



EAGLE WING TOURS D6-435 - PORT DIESEL FUEL

Sample No: VPA062099
Oil Type: No.2 DIESEL FUEL (ULTRALOW SULPHUR)

SAMPLE INFORMATION

| | | | | |
|---------------|-------------|-----|-----|-----|
| Sample Number | VPA062099 | --- | --- | --- |
| Sample Date | 05 May 2024 | --- | --- | --- |
| Machine Hours | 0 | --- | --- | --- |
| Sample Status | NORMAL | --- | --- | --- |

Sea Power Ltd
2077 Amelia Ave
SIDNEY, BC
CA V8L 3Z8
Contact: Kayla Sousa
service@seapower.ca
T: (250)656-4341
F:

FUEL CONDITION

| | | | | | |
|-------------|-----|-------|-----|-----|-----|
| Sulfur | ppm | ■ 5 | --- | --- | --- |
| Visc @ 40°C | cSt | ■ 3.6 | --- | --- | --- |

CONTAMINATION

| | | | | | |
|----------|-----|-----|-----|-----|-----|
| Lead | ppm | ■ 0 | --- | --- | --- |
| Nickel | ppm | ■ 0 | --- | --- | --- |
| Aluminum | ppm | ■ 0 | --- | --- | --- |
| Vanadium | ppm | 0 | --- | --- | --- |
| Silicon | ppm | ■ 0 | --- | --- | --- |

Diagnosis

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

OIL ANALYSIS REPORT

**VOLVO
PENTA**

GRAPHS

