

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## EAGLE WING TOURS D6-435 - DIESEL FUEL

**Sample No:** VPA062118

**Oil Type:** No.2 DIESEL FUEL (ULTRALOW SULPHUR)

### SAMPLE INFORMATION

Sample Number	VPA062118	---	---	---
Sample Date	05 May 2024	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

### FUEL CONDITION

Sulfur	ppm	■ 5	---	---	---
Visc @ 40°C	cSt	■ 3.6	---	---	---

### CONTAMINATION

Lead	ppm	■ 0	---	---	---
Nickel	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	■ 0	---	---	---

#### Sea Power Ltd

2077 Amelia Ave  
SIDNEY, BC  
CA V8L 3Z8

Contact: Kayla Sousa  
service@seapower.ca

T: (250)656-4341

F:

#### Diagnosis

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

**Depot:** VP154139

**Unique No:** 5774851

**Signed:** Kevin Marson

**Report Date:** 07 May 2024

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## GRAPHS

