

# OIL ANALYSIS REPORT



**R1-24836 PE6068E011474 - DIESEL FUEL**

**Sample No:** VPA052328

**Oil Type:** No.2 DIESEL FUEL (ULTRALOW SULPHUR)

## SAMPLE INFORMATION

Sample Number	VPA052328	---	---	---
Sample Date	10 May 2024	---	---	---
Machine Hours	72	---	---	---
Sample Status	NORMAL	---	---	---

## FUEL CONDITION

Sulfur	ppm	■ 6	---	---	---
Visc @ 40°C	cSt	■ 2.6	---	---	---

## CONTAMINATION

Lead	ppm	■ 0	---	---	---
Nickel	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	■ 0	---	---	---

**CULLEN DIESEL POWER - 695335**

9300 192 ST

SURREY, BC

CA V4N 3R8

Contact: Michelle Sayers

genservice@cullendiesel.com

T: (604)888-1211

F:

## Diagnosis

Please contact your representative for information regarding the proper sampling kits for your service.(not applicable) There is no indication of any contamination in the component(unconfirmed). Not enough sample submitted to determine fuel condition and/or classification.

**Depot:** CULSUR

**Unique No:** 5786473

**Signed:** Kevin Marson

**Report Date:** 24 May 2024

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## GRAPHS

