OIL ANALYSIS REPORT

ONAN ONAN - ROWE (S/N NOT GIVEN) - CENTER GENSET ROWE TAP352403

Sample No: VPA034656

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

SAMPLE INFORMATION VPA034656 Sample Number **FDDA TAMPA** Sample Date 19 Apr 2021 Machine Hours 457 TAMPA, FL **Oil Hours** 0 US Oil Changed Changed Contact: KYLE SUTLEY NORMAL Sample Status k.sutley@ssss.com T: (813)918-8518 **OIL CONDITION** F: Visc @ 100°C cSt 12.6 Oxidation (PA) % 73 Diagnosis CONTAMINATION Resample at the next service interval to monitor.All component wear rates Water % NEG are normal. There is no indication of % Soot % 0.1 any contamination in the oil. The Nitration (PA) % 61 condition of the oil is acceptable for Sulfation (PA) % 60 the time in service. Glycol % NEG % Fuel <1.0 Silicon ppm 19 Sodium ppm 3 Potassium 7 ppm WEAR METALS Iron ppm 8 2 Copper ppm Lead ppm 1 🔲 Tin ■ <1 ppm Aluminum 4 ppm Chromium **|** <1 ppm Molybdenum 15 ppm Nickel ■ <1 ppm Titanium ppm <1 Silver ppm 1 Manganese **||** <1 ppm Vanadium <1 ppm **ADDITIVES** Calcium 2000 ppm Magnesium 228 ppm Zinc ppm 1231 Phosphorus ppm 998 Barium ppm 0 🔲 Boron ppm 145


VP208641 Depot: Unique No: 9475344 Signed: Don Baldridge **Report Date:** 26 Apr 2021



OIL ANALYSIS REPORT



GRAPHS



Report Id: VP208641 [WUSCAR] 05236436 (Generated: 01/09/2024 07:29:27) Rev: 1

Contact/Location: KYLE SUTLEY - VP208641