OIL ANALYSIS REPORT

VOLVO PENTA 22775506 - INBOARD - PORT GEARBOX

Sample No: VPA014508

Oil Type: PENZOIL ATF

SAMPLE INFORMATION Sample Number VPA014508 Sample Date 22 Jun 2022 Machine Hours 401 200 **Oil Hours** US Oil Changed Changed NORMAL Sample Status T: **OIL CONDITION** F: Visc @ 40°C cSt 25.3 CONTAMINATION Silicon ppm 5 Sodium ppm ■ <1 Potassium 0 ppm WEAR METALS PO 23 Iron 42 ppm Copper ppm 17 Lead ppm 0 Tin **||** <1 ppm 2 Aluminum ppm Chromium ppm <1 Molybdenum 0 ppm Nickel 0 ppm 0 Titanium ppm Silver 0 ppm Manganese <1 ppm Vanadium 0 ppm **ADDITIVES** Calcium 111 ppm Magnesium ppm 0 13 Zinc ppm Phosphorus ppm 256 Barium 2 ppm 125 Boron ppm



FDDA FT PIERCE - POWER CENTER

FORT PIERCE, FL Contact: KYLE GRASER k.graser@kirbycorp.com

Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	VP208659
Unique No:	10034441
Signed:	Angela Borella
Report Date:	01 Jul 2022

Contact/Location: KYLE GRASER - VP208659

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP208659 [WUSCAR] 05580015 (Generated: 10/09/2023 08:40:00) Rev: 1

Contact/Location: KYLE GRASER - VP208659