



VOLVO PENTA 22775506 - INBOARD - STARBOARD GEARBOX

Sample No: VPA014507 **Oil Type:** PENZOIL ATF

SAMPLE INFORMA	ATION			
SAMPLE INFURMA	ATIUN			
Sample Number		VPA014507	 	
Sample Date		22 Jun 2022	 	
Machine Hours		20	 	
Oil Hours		20	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
OIL CONDITION				
Visc @ 40°C	cSt	29.4	 	
CONTAMINATION				
Silicon		1 0	 	
Sodium	ppm	<u> </u>	 	
Potassium	ppm	0	 	
Potassium	ppm		 	
WEAR METALS				
PQ		■33	 	
Iron	ppm	■ 32	 	
Copper	ppm	■34	 	
Lead	ppm	-<1	 	
Tin	ppm	-< 1	 	
Aluminum	ppm	■ 3	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	102	 	
Magnesium	ppm	102	 	
Zinc	ppm	21	 	
Phosphorus	ppm	238	 	
Barium	ppm	11	 	
Boron		108	 	
DOIOII	ppm	100	 	

FDDA FT PIERCE - POWER CENTER

FORT PIERCE, FL US Contact: KYLE GRASER k.graser@kirbycorp.com T: F:

Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP208659Unique No:10034442Signed:Angela BorellaReport Date:01 Jul 2022

OIL ANALYSIS REPORT



