OIL ANALYSIS REPORT

WARREN LUETT VOLVO PENTA 3950008024 - PORT IPS

Sample No:VPA047697Oil Type:NOT GIVEN

SAMPLE INFORMATION

Sample Number		VPA047697	 	
Sample Date		10 Jan 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	103	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	7	 	
Sodium	ppm	6	 	
Potassium	ppm	10	 	
WEAR METALS				
PQ		∎15	 	
Iron	ppm	23	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	 <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	50	 	
Magnesium	ppm	877	 	
Zinc	ppm	6	 	
Phosphorus	ppm	1555	 	
Barium	ppm	0	 	
		576		

VOLVO PENTA

BELLINGHAM YACHT SALES (OUILEETE BROS) 1801 ROEDER AVE, SUITE 174

BELLINGHAM, WA US 98225 Contact: MATT CLARK service@bellinghamyachts.com T:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP255663

 Unique No:
 10286025


 Signed:
 Sean Felton

 Report Date:
 12 Jan 2023

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP255663 [WUSCAR] 05736427 (Generated: 12/15/2023 13:29:44) Rev: 1

Contact/Location: MATT CLARK - VP255663