

# OIL ANALYSIS REPORT

# VOLVO PENTA

**SAGI GOLDBERG CODY/501927 VOLVO PENTA 51220330023 - INBOARD - GEARBOX**

**Sample No:** VPA048629

**Oil Type:** ATF

## SAMPLE INFORMATION

Sample Number	VPA048629	---	---	---
Sample Date	08 May 2023	---	---	---
Machine Hours	330	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

**Endor Marine LLC - Coastal Marine - 152124**  
4300 11th Ave. NW  
SEATTLE, WA  
US 98107  
Contact: WILLOW YANARELLA  
service@coastalmarineengine.com  
T: (206)784-3703  
F: (206)784-8823

## OIL CONDITION

Visc @ 40°C	cSt	■ 28.7	---	---	---
-------------	-----	--------	-----	-----	-----

## CONTAMINATION

Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 3	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

## WEAR METALS

PQ		■ 65	---	---	---
Iron	ppm	■ 100	---	---	---
Copper	ppm	■ 17	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 2	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 1	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 1	---	---	---
Vanadium	ppm	<1	---	---	---

## ADDITIVES

Calcium	ppm	■ 46	---	---	---
Magnesium	ppm	■ 6	---	---	---
Zinc	ppm	■ 20	---	---	---
Phosphorus	ppm	■ 167	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 65	---	---	---

**Depot:** VP794951  
**Unique No:** 10467771  
**Signed:** Don Baldrige  
**Report Date:** 15 May 2023

# OIL ANALYSIS REPORT



## GRAPHS

