



VANUTA - TOKARZ DT MERCRUISER 0L799351 - STERNDRIVE - PORT GEARBOX

Sample No: VPA048608

Oil Type: QUICKSILVER/MERCURY 90W

CAMPI E INTORNA	ATION			
SAMPLE INFORM	ATION			
Sample Number		VPA048608	 	
Sample Date		22 Jun 2023	 	
Machine Hours		666	 	
Oil Hours		15	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
	C.	-4		
Visc @ 40°C	cSt	■ 155	 	
CONTAMINATION				
Silicon	ppm	1	 	
Sodium	ppm	■<1	 	
Potassium	ppm	■3	 	
WEAR METALS				
PQ		□ 26	 	
Iron	nnm	■ 88	 	
Copper	ppm	10	 	
Lead	ppm	<u> </u>	 	
Tin		■ <1	 	
Aluminum	ppm	5	 	
Chromium	ppm	1	 	
Molybdenum		56	 	
Nickel	ppm ppm	■ <1	 	
Titanium	ppm	<1	 	
Silver	ррт	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIO	1-1-			
Calcium	ppm	13	 	
Magnesium	ppm	10	 	
Zinc	ppm	14	 	
Phosphorus	ppm	247	 	
Barium	ppm	0	 	
Boron	ppm	1	 	

CHICAGO YACHT WORKS

2550 S ASHLAND AVE CHICAGO, IL US 60608 Contact: JONATHAN PAIGE jonathan@chicagoyachtworks.com T: (312)666-6670 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP1080862Unique No:10535179Signed:Jonathan HesterReport Date:30 Jun 2023

OIL ANALYSIS REPORT



