



WAVY ONAN E180352955 - GENSET

Sample No: VPA055521
Oil Type: NOT GIVEN

SAMPLE INFORMAT	TION			
Sample Number		VPA055521	 	
Sample Date		28 Jun 2023	 	
Machine Hours		767	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	■ 13.61	 	
Base Number (BN)	mg KOH/g	7.7	 	
Oxidation (PA)	%	63	 	
CONTAMINATION				
CONTAMINATION				
Soot %	%	0.1	 	
Nitration (PA)	%	57	 	
Sulfation (PA)	%	52	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	□ 7	 	
Sodium		■ <1	 	
Potassium	ppm	2	 	
FOLASSIUIII	ppm		 	
WEAR METALS				
Iron	ppm	■8	 	
Copper	ppm	2	 	
Lead	ppm	<1	 	
Tin	ppm	■<1	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	= <1	 	
Molybdenum	ppm	57	 	
Nickel	ppm	<1	 	
Titanium		0	 	
Silver	ppm	0	 	
	ppm	= 0 <1		
Manganese Vanadium	ppm	<1 0	 	
vanadium	ppm	U	 	
ADDITIDDA				
Calcium	ppm	1213	 	
Magnesium	ppm	675	 	
Zinc	ppm	1114	 	
Phosphorus	ppm	942	 	
Barium	ppm	0	 	
Boron	ppm	24	 	
DOTOTI	PPIII	- 7		

Harry's Marine Service LLC

1141 N. Citrus St.
Orange, CA
US 92887
Contact: TARAH AULD
info@harrysmarine.com
T: (714)771-7899
F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP867279Unique No:10537676Signed:Doug BogartReport Date:29 Jun 2023

OIL ANALYSIS REPORT



