OIL ANALYSIS REPORT

VOLVO PENTA 3950008499 - PORT IPS

Sample No:	VPA029839
Oil Type:	NOT GIVEN

SAMPLE INFORMATION Sample Number VPA029839 Sample Date 28 Jun 2023 Machine Hours 192 **Oil Hours** 0 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 103 CONTAMINATION Silicon ppm 2 Sodium ppm 1 Potassium 2 ppm WEAR METALS PO 12 Iron 19 ppm Copper ppm 2 Lead ppm 0 Tin 0 ppm 0 Aluminum ppm Chromium ppm **||** <1 Molybdenum 0 ppm Nickel **||** <1 ppm 0 Titanium ppm Silver 0 ppm Manganese 2 ppm Vanadium 0 ppm **ADDITIVES** Calcium 14 ppm Magnesium ppm 169 Zinc ppm 0 Phosphorus ppm 1527 Barium 0 ppm 409 Boron ppm



Johnson & Towers, Inc 2021 Briggs Road MT.LAUREL, NJ US 08054 Contact: BRENT BUZBY BBUZBY@JOHNSONTOWERS.COM T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP855105

 Unique No:
 10538558

 Signed:
 Don Baldridge


 Report Date:
 04 Jul 2023

Contact/Location: BRENT BUZBY - VP855105

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP855105 [WUSCAR] 05888075 (Generated: 07/04/2023 15:21:53) Rev: 1

Contact/Location: BRENT BUZBY - VP855105