# **OIL ANALYSIS REPORT**

### JC HULZINGA VOLVO PENTA 3950006458 - STARBOARD IPS

Sample No:VPA046898Oil Type:NOT GIVEN

#### SAMPLE INFORMATION Sample Number VPA046898 28 Jun 2023 Sample Date Machine Hours 235 **Oil Hours** 0 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 106 CONTAMINATION Silicon ppm <1 Sodium ppm ■ <1 Potassium ■<1 ppm WEAR METALS PO 13 Iron ppm **17** Copper ppm 3 Lead ppm 0 Tin 0 ppm 0 Aluminum ppm Chromium ppm **||** <1 Molybdenum <1 ppm Nickel 0 🔲 ppm Titanium 0 ppm Silver 0 ppm Manganese <1 ppm Vanadium 0 ppm ADDITIVES Calcium 20 ppm 9 Magnesium ppm Zinc ppm 0 Phosphorus ppm 1472 Barium 0 ppm 252 Boron ppm

## VOLVO PENTA

**YACHT BASIN MARINA** 

1866 OTTAWA BEACH RD HOLLAND, MI US 49424 Contact: OIL SAMPLE/PART kyle@yachtbasinmarina.com T: (616)786-2205 F:

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP718610

 Unique No:
 10539888

 Signed:
 Angela Borella


 Report Date:
 06 Jul 2023

Contact/Location: OIL SAMPLE/PART - VP718610

# **OIL ANALYSIS REPORT**







Report Id: VP718610 [WUSCAR] 05889405 (Generated: 07/06/2023 16:59:28) Rev: 1

Contact/Location: OIL SAMPLE/PART - VP718610