OIL ANALYSIS REPORT

MARK MILLER ZF 20409439 - INBOARD - PORT GEARBOX

 Sample No:
 VPA039727

 Oil Type:
 AMELIA 40

SAMPLE INFORMATION Sample Number VPA039727 12 Jul 2023 Sample Date Machine Hours 51 0 **Oil Hours** Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 85.6 CONTAMINATION Silicon ppm 11 Sodium ppm 0 Potassium 2 ppm WEAR METALS PO 16 Iron 14 ppm Copper ppm 56 Lead ppm 2 Tin 3 ppm 4 Aluminum ppm Chromium ppm 0 🔲 Molybdenum 50 ppm Nickel 0 🔲 ppm Titanium 0 ppm Silver 0 ppm Manganese <1 ppm Vanadium 0 ppm **ADDITIVES** Calcium 3627 ppm 26 Magnesium ppm Zinc ppm 1171 Phosphorus ppm 1061 Barium 0 ppm 514 Boron ppm

VOLVO PENTA

TAMPA, FL US Contact: KYLE SUTLEY k.sutley@ssss.com T: (813)918-8518 F:

FDDA TAMPA

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP208641

 Unique No:
 10553531


 Signed:
 Don Baldridge

 Report Date:
 17 Jul 2023

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP208641 [WUSCAR] 05897721 (Generated: 07/17/2023 11:43:31) Rev: 1

Contact/Location: KYLE SUTLEY - VP208641