



HARDESTY HARDESTY VOLVO PENTA 3950005510 - PORT IPS

Sample No: VPA055237
Oil Type: NOT GIVEN

SAMPLE INFORM <i>e</i>	ATION			
Sample Number		VPA055237	 	
Sample Date		12 Jul 2023	 	
Machine Hours		72	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL COMPLETION				
OIL CONDITION				
Visc @ 40°C	cSt	107.3	 	
CONTAMINATION				
Silicon	ppm	2	 	
Sodium	ppm	<u>1</u>	 	
Potassium	ppm	3	 	
	ррпп		 	
WEAR METALS				
PQ		14	 	
Iron	ppm	11	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	<1	 	
Aluminum	ppm	<1	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	2	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	9	 	
Magnesium	ppm	120	 	
Zinc	ppm	2	 	
Phosphorus	ppm	1416	 	
Barium	ppm	0	 	
Boron	ppm	324	 	
	P P			

Harry's Marine Service LLC

1141 N. Citrus St.
Orange, CA
US 92887
Contact: TARAH AULD
info@harrysmarine.com
T: (714)771-7899
F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP867279Unique No:10559201Signed:Doug BogartReport Date:13 Jul 2023

OIL ANALYSIS REPORT



