

# OIL ANALYSIS REPORT

# VOLVO PENTA

## 92 LAZZARA CUMMINS ONAN H110240910 - STARBOARD GENSET

**Sample No:** VPA046306  
**Oil Type:** DIESEL ENGINE OIL SAE 40

### SAMPLE INFORMATION

Sample Number	VPA046306	---	---	---
Sample Date	11 Jul 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

### OIL CONDITION

Visc @ 100°C	cSt	█ 13.4	---	---	---
Base Number (BN)	mg KOH/g	█ 10.1	---	---	---
Oxidation (PA)	%	55	---	---	---

### CONTAMINATION

Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	41	---	---	---
Sulfation (PA)	%	51	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	<1.0	---	---	---
Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---

### WEAR METALS

Iron	ppm	█ 2	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 52	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---

### ADDITIVES

Calcium	ppm	█ 1241	---	---	---
Magnesium	ppm	█ 806	---	---	---
Zinc	ppm	█ 1175	---	---	---
Phosphorus	ppm	█ 1022	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 8	---	---	---

**Marine International Diesels Inc.**  
3600 HACIENDA BLVD UNIT G  
DAVIE, FL  
US 33314  
Contact: service manager  
service@midiflorida.com  
T:  
F:

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

**Depot:** VP694356  
**Unique No:** 10561137  
**Signed:** Doug Bogart  
**Report Date:** 18 Jul 2023

# OIL ANALYSIS REPORT

# VOLVO PENTA

## GRAPHS

