



## 92 LAZZARA VOLVO PENTA 7011235489 - CENTER RIGHT DIESEL ENGINE

Sample No: VPA046309

**Oil Type:** DIESEL ENGINE OIL SAE 40

SAMPLE INFORMAT	TION			
Sample Number		VPA046309	 	
Sample Date		11 Jul 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.0</b>	 	
Base Number (BN)	mg KOH/g	10.2	 	
Oxidation (PA)	%	56	 	
Oxidation (FA)	70		 	
CONTAMINATION				
Soot %	%	<b>■</b> 0.1	 	
Nitration (PA)	%	43	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>■</b> <1	 	
Potassium	ppm	<b>2</b>	 	
WEAR METALS				
Iron	ppm	<b>■4</b>	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>■ &lt;1</b>	 	
Aluminum		<b>4</b>	 	
Chromium	ppm	<b>■</b> <1	 	
	ppm	_		
Molybdenum	ppm	<b>59</b>	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>■&lt;1</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>■</b> 1064	 	
Magnesium	ppm	<b>891</b>	 	
Zinc	ppm	<b>1186</b>	 	
Phosphorus	ppm	<b>1032</b>	 	
Barium	ppm	<b>■</b> 0	 	
Boron	ppm	1	 	
201011	PPIII			

## **Marine International Diesels Inc.**

3600 HACIENDA BLVD UNIT G DAVIE, FL

US 33314

Contact: service manager service@midiflorida.com

т. F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP694356Unique No:10561138Signed:Doug BogartReport Date:18 Jul 2023

## **OIL ANALYSIS REPORT**



