



## DAMP ONAN D100111873 - GENSET

Sample No: VPA041436

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	LION			
Sample Number		VPA041436	 	
Sample Date		13 Jul 2023	 	
Machine Hours		1248	 	
Oil Hours		120	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
OIL CONDITION				
Visc @ 100°C	cSt	<b>14.3</b>	 	
Base Number (BN)	mg KOH/g	■8.9	 	
Oxidation (PA)	%	68	 	
CONTAMINATION				
Soot %	%	■ 0.1	 	
Nitration (PA)	%	58	 	
Sulfation (PA)	%	55	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>14</b>	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>■</b> 3	 	
WEAR METALS				
Iron	ppm	<b>■4</b>	 	
Copper	ppm	<b>■</b> <1	 	
Lead	ppm	□0	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	<b>■41</b>	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium		<b>■</b> 0	 	
Silver	ppm	0	 	
	ppm			
Manganese Vanadium	ppm	<b>□</b> <1 0	 	
vanadium	ppm	U	 	
ADDITIVES				
Calcium	ppm	<b>1345</b>	 	
Magnesium	ppm	<b>610</b>	 	
Zinc	ppm	■881	 	
Phosphorus	ppm	<b>736</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>1</b> 71	 	
20.011	77111			

## **Marine International Diesels Inc.**

3600 HACIENDA BLVD UNIT G DAVIE, FL US 33314 Contact: ASHANTI BURKE aburke@midiflorida.com T: (954)761-1086 F: (954)761-1186

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP694356Unique No:10561140Signed:Doug BogartReport Date:18 Jul 2023

## OIL ANALYSIS REPORT



