

OIL ANALYSIS REPORT

VOLVO PENTA

VOLVO PENTA 3195000951 - CENTER LEFT IPS

Sample No: VPA046311

Oil Type: NOT GIVEN

SAMPLE INFORMATION

Sample Number	VPA046311	---	---	---
Sample Date	11 Jul 2023	---	---	---
Machine Hours	2596	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 40°C	cSt	█ 107	---	---	---
-------------	-----	-------	-----	-----	-----

CONTAMINATION

Silicon	ppm	█ 25	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 1	---	---	---

WEAR METALS

PQ		█ 21	---	---	---
Iron	ppm	█ 116	---	---	---
Copper	ppm	█ 19	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	█ 0	---	---	---

ADDITIVES

Calcium	ppm	█ 9	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 35	---	---	---
Phosphorus	ppm	█ 1330	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 295	---	---	---

Marine International Diesels Inc.
3600 HACIENDA BLVD UNIT G
DAVIE, FL
US 33314
Contact: JEF BURKE
midjef@gmail.com;canastasio@wearcheckusa.com
T:
F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP694356
Unique No: 10561606
Signed: Doug Bogart
Report Date: 18 Jul 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

