



JEWELL VOLVO PENTA 25961 - INBOARD - PORT GEARBOX

Sample No: VPA050601
Oil Type: SAE 30W

SAMPLE INFORMA	ATION			
Sample Number		VPA050601	 	
Sample Number		14 Jul 2023	 	
Machine Hours		540	 	
Oil Hours		5	 	
Oil Changed		Not Changd	 	
		ABNORMAL	 	
Sample Status		ADNURWAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	23.93	 	
CONTAMINATION				
Silicon		□ 6	 	
Sodium	ppm			
Potassium	ppm	□ 3 □ 2	 	
Potassium	ppm		 	
WEAR METALS				
PQ		■31	 	
Iron	ppm	102	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	△ 367	 	
Tin	ppm	1	 	
Aluminum	ppm	1	 	
Chromium	ppm	□ <1	 	
Molybdenum	ppm	■ 0	 	
Nickel	ppm	0	 	
Titanium	ppm	■ 0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	217	 	
Magnesium	ppm	4	 	
Zinc	ppm	■35	 	
Phosphorus	ppm	239	 	
Barium	ppm	92	 	
Boron	ppm	70	 	
DOTOIT	ppiii			

Outstanding Marine

PO Box 274
GALENA, MD
US 21635
Contact: Ronda Bolinger rlwb@verizon.net
T:
F:

Diagnosis

No corrective action is recommended at this time. We recommend an early resample to monitor this condition. Clutch wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP153685Unique No:10561737Signed:Doug BogartReport Date:17 Jul 2023

OIL ANALYSIS REPORT



