



VANZANDT ONAN 1040689934 - GENSET

Sample No: VPA045914
Oil Type: NOT GIVEN

SAMPLE INFORMAT	TION			
		\/D4045044		
Sample Number		VPA045914	 	
Sample Date		19 Jul 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	■13.4	 	
Base Number (BN)	mg KOH/g	8.5	 	
Oxidation (PA)	%	63	 	
CONTAMINATION				
Soot %	%	0.1	 	
Nitration (PA)	%	48	 	
Sulfation (PA)	%	55	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	4	 	
Sodium	ppm	3	 	
Potassium		6	 	
rotassiuiii	ppm		 	
WEAR METALS				
Iron	ppm	■ 3	 	
Copper	ppm	2	 	
Lead	ppm	<1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	1 <1	 	
Molybdenum		5	 	
Nickel	ppm		 	
Titanium	ppm	<1	 	
	ppm	· ·		
Silver	ppm	■0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	2227	 	
Magnesium	ppm	36	 	
Zinc	ppm	1175	 	
Phosphorus	ppm	979	 	
Barium	ppm	0	 	
Boron	ppm	241	 	

MAKO MARINE

117 HUDSON AVE FREEPORT, NY US 11520 Contact: PAUL FLOOD makomarine@optonline.net T: (516)378-7331 F: x:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP1134331

 Unique No:
 10565397

 Signed:
 Doug Bogart

 Report Date:
 25 Jul 2023

OIL ANALYSIS REPORT



