



## ZF 20206759 - INBOARD - PORT GEARBOX

Sample No: VPA046429
Oil Type: NOT GIVEN

SAMPLE INFORM	ATION			
Sample Number		VPA046429	 	
Sample Date		20 Jul 2023	 	
Machine Hours		770	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
Sample Status		NORWAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	■94.1	 	
CONTAMINATION				
Silicon	ppm	<b>□</b> 4	 	
Sodium	ppm	 8	 	
Potassium	ppm	<b>0</b>	 	
WEAR METALS				
PQ		<b>■17</b>	 	
	10 10 100	■17		
Iron	ppm		 	
Copper Lead	ppm	<b>■</b> 267 <b>■</b> 0	 	
Tin	ppm	<b>■</b> 15	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	65	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0		
Silver	ppm	0	 	
	ppm	0	 	
Manganese Vanadium	ppm ppm	0	 	
variaululli	ррпп	<u> </u>	 	
ADDITIVES				
Calcium	ppm	2155	 	
Magnesium	ppm	357	 	
Zinc	ppm	1007	 	
Phosphorus	ppm	870	 	
Barium	ppm	0	 	
Boron	ppm	299	 	

Marine International Diesels Inc. 3600 HACIENDA BLVD UNIT G

DAVIE, FL US 33314

Contact: ASHANTI BURKE aburke@midiflorida.com T: (954)761-1086

F: (954)761-1086

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal for OEM. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP694356Unique No:10576968Signed:Doug BogartReport Date:31 Jul 2023

## **OIL ANALYSIS REPORT**



