



## H150859743 - GENSET

Sample No: VPA039814

**Oil Type:** VOLVO PENTA SAE 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA039814	 	
Sample Date		10 Jul 2023	 	
Machine Hours		1399	 	
Oil Hours		69	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>12.6</b>	 	
Base Number (BN)	mg KOH/g	9.3	 	
Oxidation (PA)	%	51	 	
CONTAMINATION				
	0/			
Soot %	%	<b>0.1</b>	 	
Nitration (PA)	%	44 49	 	
Sulfation (PA)	%		 	
Glycol Fuel	%	NEG <1.0	 	
Silicon		<1.0	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>■</b> <1	 	
Fotassium	ррпп		 	
WEAR METALS				
Iron	ppm	<b>2</b>	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	<b>47</b>	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	<1	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■</b> <1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<b>1266</b>	 	
Magnesium	ppm	<b>■784</b>	 	
Zinc	ppm	<b>1145</b>	 	
Phosphorus	ppm	<b>947</b>	 	
Barium	ppm	<b>■</b> 0	 	
Boron	ppm	<b>2</b>	 	

## SIEBERT YACHT MANAGEMENT

2875 JUPITER PARK DR, SUITE 1700 JUPITER, FL US 33458 Contact: JAY SIEBERT jay@siebertyachtmanagement.com T: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP1190184Unique No:10586264Signed:Don BaldridgeReport Date:04 Aug 2023





