

OIL ANALYSIS REPORT

VOLVO PENTA

TESHAWN CAMERON VOLVO PENTA 3940027531 - PORT IPS

Sample No: VPA055073

Oil Type: VOLVO API GL-5 SAE 75W90

SAMPLE INFORMATION

Sample Number	VPA055073	---	---	---
Sample Date	04 Aug 2023	---	---	---
Machine Hours	500	---	---	---
Oil Hours	550	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	SEVERE	---	---	---

OIL CONDITION

Visc @ 40°C	cSt	■ 98.6	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	▲ 0.168	---	---	---
Silicon	ppm	■ 27	---	---	---
Sodium	ppm	■ 56	---	---	---
Potassium	ppm	■ 8	---	---	---

WEAR METALS

PQ		■ 32	---	---	---
Iron	ppm	● 1047	---	---	---
Copper	ppm	■ 45	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	■ 14	---	---	---
Chromium	ppm	■ 8	---	---	---
Molybdenum	ppm	■ 7	---	---	---
Nickel	ppm	■ 9	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	■ 12	---	---	---
Vanadium	ppm	<1	---	---	---

ADDITIVES

Calcium	ppm	■ 46	---	---	---
Magnesium	ppm	■ 34	---	---	---
Zinc	ppm	■ 54	---	---	---
Phosphorus	ppm	■ 1335	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 175	---	---	---

PARTS & POWER

PO BOX 1305498, PMB1000-00
ST THOMAS, VI
US 00803
Contact: KARIM PERSAUD
info@partsandpower.com
T: (284)494-2830
F:

Diagnosis

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a trace of moisture present in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: VP981217
Unique No: 10615776
Signed: Jonathan Hester
Report Date: 23 Aug 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

