

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

**SPROAT 531968 VOLVO PENTA 3200000367 - PORT IPS**

**Sample No:** VPA056993

**Oil Type:** VOLVO API GL-5 SAE 75W90

## SAMPLE INFORMATION

Sample Number	VPA056993	---	---	---
Sample Date	16 Aug 2023	---	---	---
Machine Hours	968	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	SEVERE	---	---	---

### Jas Marine Service Inc

3131 SW 2Nd Ave.

FORT LAUDERDALE, FL

US 33315

Contact: JASON TOLEDO

jason@jasmarine.com

T: (954)462-1112

F:

## OIL CONDITION

Visc @ 40°C	cSt	■ 100	---	---	---
-------------	-----	-------	-----	-----	-----

## CONTAMINATION

Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 11	---	---	---
Potassium	ppm	■ 2	---	---	---

## WEAR METALS

PQ		■ 47	---	---	---
Iron	ppm	● 530	---	---	---
Copper	ppm	■ 30	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 8	---	---	---
Chromium	ppm	■ 3	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ 4	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 4	---	---	---
Vanadium	ppm	■ <1	---	---	---

## ADDITIVES

Calcium	ppm	■ 8	---	---	---
Magnesium	ppm	■ 7	---	---	---
Zinc	ppm	■ 63	---	---	---
Phosphorus	ppm	■ 1444	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 263	---	---	---

## Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

**Depot:** VP426065

**Unique No:** 10615779

**Signed:** Jonathan Hester

**Report Date:** 23 Aug 2023

# OIL ANALYSIS REPORT

# VOLVO PENTA

## GRAPHS

