



## **VOLVO PENTA 3940014762 - PORT IPS**

Sample No: VPA044292

**Oil Type:** VOLVO PENTA GL-5 SAE 75W90

SAMPLE INFORM	ATION			
SAMPLE INFURMA	ATTUN			
Sample Number		VPA044292	 	
Sample Date		22 Aug 2023	 	
Machine Hours		551	 	
Oil Hours		10	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>106.5</b>	 	
CONTAMINATION				
Water	%	<b>△</b> 0.308	 	
Silicon	ppm	16	 	
Sodium	ppm	■19	 	
Potassium	ppm	■3	 	
11/200 1/200				
WEAR METALS				
PQ		<b>17</b>	 	
Iron	ppm	<b>■35</b>	 	
Copper	ppm	10	 	
Lead	ppm	<1	 	
Tin	ppm	<1	 	
Aluminum	ppm	1	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>1</b>	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>4</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>11</b>	 	
Magnesium	ppm	41	 	
Zinc	ppm	<b>■34</b>	 	
Phosphorus	ppm	<b>1632</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>487</b>	 	

## **SMART DIESEL SERVICE** 102 NW 133RD AVE, UNIT 103

PLANTATION, FL US 33325 Contact: ANDRES GARMENDIA smartdieselservice@gmail.com T: (954)258-8100 F:

## Diagnosis

We advise that you check for the source of water entry. Resample at the next service interval to monitor.All component wear rates are normal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VPSMAPLAUnique No:10617804Signed:Doug BogartReport Date:23 Aug 2023

## **OIL ANALYSIS REPORT**



