

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## TWIN DISC - INBOARD (S/N NOT GIVEN) - STARBOARD GEARBOX

**Sample No:** VPA051692

**Oil Type:** DIESEL ENGINE OIL SAE 15W40

### SAMPLE INFORMATION

Sample Number	VPA051692	---	---	---
Sample Date	22 Aug 2023	---	---	---
Machine Hours	2514	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	ATTENTION	---	---	---

### OIL CONDITION

Visc @ 40°C	cSt	■ 91.5	---	---	---
-------------	-----	--------	-----	-----	-----

### CONTAMINATION

Silicon	ppm	■ 4	---	---	---
Sodium	ppm	■ 3	---	---	---
Potassium	ppm	■ 0	---	---	---

### WEAR METALS

PQ		■ 14	---	---	---
Iron	ppm	■ 10	---	---	---
Copper	ppm	■ 32	---	---	---
Lead	ppm	▲ 100	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 3	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 9	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ <1	---	---	---
Vanadium	ppm	0	---	---	---

### ADDITIVES

Calcium	ppm	■ 3391	---	---	---
Magnesium	ppm	■ 33	---	---	---
Zinc	ppm	■ 1245	---	---	---
Phosphorus	ppm	■ 1046	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 118	---	---	---

### BAY AREA MARINE SERVICES

420 DONAHUE ST

SAUSALITO, CA

US 94965

Contact: LUIS MARTINEZ

luis@bayareamarineservices.com

T: (415)272-5830

F:

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The lead level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VPBAYSAU

**Unique No:** 10622835

**Signed:** Don Baldrige

**Report Date:** 31 Aug 2023

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## GRAPHS

