



## PRU 61552-A3 ZF/VOLVO PENTA 51220414639 - INBOARD V-DRIVE - PORT GEARBOX

**Sample No:** VPA05939303

Oil Type: VALVOLINE DEXRON III/MERCON ATF

SAMPLE INFORM	TION			
	ATTUN			
Sample Number		VPA05939303	VPA05939307	 
Sample Date		03 Apr 2023	16 Mar 2023	 
Machine Hours		141	11	 
Oil Hours		141	11	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	SEVERE	 
OIL CONDITION				
Visc @ 40°C	cSt	<b>26.1</b>	■34.0	 
CONTAMINATION				
Silicon	ppm	<b>5</b>	<b>3</b> 5	 
Sodium	ppm	<b>2</b>	<b>2</b>	 
Potassium	ppm	<b></b>	<b>2</b>	 
WEAR METALS				
PQ		<b>1</b> 2	<b>1</b> 5	 
Iron	ppm	<b>44</b>	<b>1</b> 7	 
Copper	ppm	<b>17</b>	<b>■</b> 36	 
Lead	ppm	<b>-&lt;1</b>	<b>1</b>	 
Tin	ppm	<b>-&lt;1</b>	< 1	 
Aluminum	ppm	<b>3</b>	<b>3</b>	 
Chromium	ppm	<b>0</b>	<b>0</b>	 
Molybdenum	ppm	■0	<b>0</b>	 
Nickel	ppm	<b>0</b>	<b>0</b>	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	0	<1	 
Vanadium	ppm	0	0	 
ADDITIVES				
Calcium	ppm	86	<u> </u>	 
Magnesium	ppm	<b>2</b>	<b>2</b>	 
Zinc	ppm	<b>■</b> 5	<b>2</b> 1	 
Phosphorus	ppm	<b>217</b>	<b>2</b> 45	 
Barium	ppm	O	0	 
Darium				

## Marine Max, Inc.

dba Marine Max Vacations, 18167 US highway 19N, Ste 300 Clearwater, FL US 33764 Contact: Dave Thelen David.Thelen@marinemax.com

F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP841065Unique No:10629915Signed:Sean FeltonReport Date:01 Sep 2023

## OIL ANALYSIS REPORT



