



## 43528 CUMMINS/ONAN A200709118 - GENSET

Sample No: VPA055780

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	TION			
Cananda Nivershan		VD4055700		
Sample Number		VPA055780	 	
Sample Date		29 Aug 2023	 	
Machine Hours		92	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>12.5</b>	 	
Base Number (BN)	mg KOH/g	<b>10.2</b>	 	
Oxidation (PA)	%	61	 	
CONTRAGNATION				
CONTAMINATION				
Soot %	%	<b>0.1</b>	 	
Nitration (PA)	%	58	 	
Sulfation (PA)	%	52	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>27</b>	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>■</b> <1	 	
1 0 (433)4111	ррш			
WEAR METALS				
Iron	ppm	<b>11</b>	 	
Copper	ppm	<b>11</b>	 	
Lead	ppm	■0	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	8	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	<b>■</b> 56	 	
Nickel	ppm	■0	 	
Titanium	ppm	<b>■&lt;1</b>	 	
Silver	ppm	<b>0</b>	 	
Manganese		<b>3</b>	 	
Vanadium	ppm	0	 	
	ррш	0	 	
ADDITIVES				
Calcium	ppm	<b>1999</b>	 	
Magnesium	ppm	<b>■</b> 505	 	
Zinc	ppm	<b>1264</b>	 	
Phosphorus	ppm	<b>1027</b>	 	
Barium	ppm	■8	 	
Boron	ppm	<b>□</b> 75	 	
	- P			

## **COASTAL CAROLINA YACHT SALES**

145 LOCKWOOD BLVD CHARLESTON, SC US 29403 Contact: STEVE VASAS steve@ccyachtsales.com T: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP568144Unique No:10644692Signed:Don BaldridgeReport Date:14 Sep 2023

## OIL ANALYSIS REPORT



